Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	54	((actuat\$3 or motor) near2 electric\$4) same cam same shaft same (perpendicular\$2 or horizontal\$2 or orthogonal\$2)	US-PGPUB	OR	ON	2005/10/01 20:48
S1	1063	shibata-akira.in.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/26 11:15
S2	28	S1 and "123"/\$.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/26 14:02
S3	118	suzuki-yasuyoshi.in.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/26 14:02
S4	1	S3 and "123"/\$.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR .	ON	2005/09/26 14:02
S5	13	"6425357"	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/26 14:02
S6	9	("4708101"   "5367991"   "5431132"   "5474037"   "5592906"   "5803029"   "6009842"   "6016779"   "6182623").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/26 14:09
S7	0	jp-63182371-\$.did.	US-PGPUB; USPAT; USOCR	OR	ON .	2005/09/26 14:09
S8	0	jp-0618999-\$.did.	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/26 14:09
S9	0	jp-618999-\$.did.	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/26 14:09
S10	0	jp-06018999-\$.did.	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/26 14:09
S11	0	jp-060018999-\$.did.	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/26 14:10
S12	0	jp-60164003-\$.did.	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/26 14:10

S13	0	jp-07132470-\$.did.	US-PGPUB; USPAT;	OR	ON	2005/09/26 14:10
S14	0	jp-7132470-\$.did.	USOCR US-PGPUB; USPAT; USOCR	OR	ON	2005/09/26 14:11
S15	2	"6328006"	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/26 14:11
S16	167	riddle-\$.xa.	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/26 14:12
S17	76	S16 and 123/90.17,90.18.ccls.	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/26 14:12
S18	91	S16 not S17	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/26 14:19
S19		("3978829"   "4770060"   "4771742"   "4878461"   "4917058"   "5329890"   "5417186"   "5924395"   "5979382"   "6138622"   "6138623"   "6199522"   "6216654").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/26 14:45
S20	1792	123/90.16.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/26 14:45
S21	273	123/90.18.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/26 14:45
S22	839	123/90.11.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/26 14:45
S23	2045	123/90.17.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/26 14:45
S24	. 35	S20 and S21	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/26 14:58
S25	3	("5836274"   "6425357"   "6715456").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/26 14:54

S26	32	S20 and S22	US-PGPUB;	OR	ON	2005/09/26 14:55
320		320 0110 322	USPAT; USOCR			2000,00,00
S27	30	S26 not S24	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/26 14:55
S28	7	S21 and S22	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/26 15:01
S29	58	123/90.21.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/26 15:05
S30	3874	123/90.15,90.27,90.31.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/26 15:05
S31	6712	S20 or S21 or S22 or S23 or S30	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/26 15:06
S32	6501	motor same shaft same cam same (axial\$2 or horizontal\$2)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/26 15:07
S33	64	S31 and S32	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/26 15:41
S34	14	US-5417187-\$.DID. OR US-5562071-\$.DID. OR US-5680834-\$.DID. OR US-6012437-\$.DID. OR US-6129061-\$.DID. OR US-6371066-\$.DID. OR US-6795291-\$.DID.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/26 15:23
S35	7	"6491022"	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/26 15:24
S36	8	"6178934"	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON .	2005/09/26 15:25
S37	2	"20030019475"	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/26 15:26

S38	0	in 13161134 ¢ did	US-PGPUB;	OR	ON	2005/00/26 15:26
330	U	jp-12161124-\$.did.	USPAT; EPO; JPO; DERWENT	OK	ON	2005/09/26 15:26
S39	0	jp-15083149-\$.did.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/26 15:27
S40	0	jp-150083149-\$.did.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/26 15:27
S41	0	jp-1583149-\$.did.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/26 15:27
S42	80	S32 and "310"/\$.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/26 15:46
S43	80	S42 not S33	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/26 15:40
S44	1174	drive adj cam same motor same gear	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/26 15:44
S45	7	S31 and S44	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/26 15:49
S46	400	drive adj cam same actuat\$3 same gear	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/26 15:44
S47	10	S31 and S46	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/26 15:44
S48	6	S44 and "310"/\$.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/26 15:46
S49	3	S46 and "310"/\$.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/26 15:47

S50	4299	control adj shaft same (motor or actuat\$3)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/26 15:48
S51	231	S31 and S50	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/26 15:50
S52	6	("20030019475"   "20040244473"   "6491022"   "6595172"   "6779508"   "6834627").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/26 15:51
S53	4	("5549080"   "5715779"   "6834627"   "6877466").PN.	US-PGPUB; USPAT; USOCR	OR	ON <sub>.</sub>	2005/09/26 15:52
S54	5	("5363817"   "5664529"   "5715779"   "6301543"   "6776130").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/26 15:53
S55	2	("6564763"   "6691022").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/26 15:54
S56	2	("5636603"   "5992361").PN.	US-PGPUB; USPAT; USOCR	OR	ON	2005/09/26 16:00
S57	2631	cam with (wall or housing) with (horizontal\$2 or lateral\$2 or linear\$2 or axial\$2) with shaft	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/29 10:13
S58	13	S57 and "310"/\$.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/29 10:19
S59	1802	123/90.16.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/29 10:15
S60	273	123/90.18.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/29 10:15
S61	844	123/90.11.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/29 10:15
S62	2050	123/90.17.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/29 10:15

S63	3891	123/90.15,90.27,90.31.ccls.	US-PGPUB;	OR	ON	2005/09/29 10:15
303	3031	123/30.13,30.27,30.31.665.	USPAT; EPO; JPO; DERWENT		ON	2003/03/23 10:15
S64	6735	S59 or S60 or S61 or S62 or S63	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/29 10:15
S65	68	S64 and S57	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/29 10:19
S66	812	motor with gear with spindle with reduction	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/29 10:20
S67	0	S64 and S66	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/29 10:48
S68	11	S66 and "310"/\$.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/29 10:21
S69	3854	motor and (gear with reduc\$4) and (control\$4 near2 shaft)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/29 10:21
S70	65	S69 and "310"/\$.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/29 10:21
S71	49	S64 and S69	US-PGPUB; USPAT; EPO; JPO; DERWENT	ÖR	ON	2005/09/29 10:48
S72	39010	denso-\$.as.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/29 10:48
S73	85	S64 and S72	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/29 11:17
S74	0	jp-12110528-\$.did.	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/29 10:59

S75	18	"6012437"	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/29 11:01
S76	13	"6129061"	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/29 11:02
S77	3	"6371066"	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/29 11:07
S78	187	S61 and (S59 or S60 or S62 or S63)	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/29 11:16
S79	27,6	cam same ax\$1s same gear same (motor or actuator) same shaft	US-PGPUB	OR	ON	2005/09/29 11:17
S80	16	S64 and S79	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	ON	2005/09/29 11:17